

TECHNICAL INFORMATION N°2005 - 02

Chassis : 29DM182 (ITC008)


Symptom / Problem Observed :

The set switches randomly to security mode.


Solution :

- On East-West module, change RL112 resistor from 82K Ω to 75K Ω 5% 0.250W (**PART No 15009190**).
- On chassis, remove CL022 capacitor.

EAST-WEST MODULE



CHASSIS



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 1 1 0	1 5 0 0 9 1 9 0	0 1	R L 1 1 2	D F L	Y	A

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>