


TECHNICAL INFORMATION N°2005 - 44

Chassis : ITC008 - 21"model
(With Videocolor Tube A51EFS13X701 and DST Orega)

Symptom / Problem Observed :
Horizontal over scanning.

Solution :
- Change CL024 capacitor from 510nF to 560nF 5% 250V (**PART No 10376360**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;

we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	1 0 3 7 6 3 6 0	0 1	C L 0 2 4	D F L	Y	K

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>