


TECHNICAL INFORMATION N°2005 - 47

**Chassis : ITC008 - 21" XF model
(With Videcolor Tube A51ELD032X001)**

Symptom / Problem Observed :
Horizontal over scanning.

Solution :
- Delete the capacitor in position CL023.
- Add capacitor 240nF 5% 250V in position CL024 **PART No 56041060.**



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;

we have included it to make fault report easier and the data more reliable.

| Symptom | Part code number | Qty | Position | Section | D.Code | R.Code |
|---------|------------------|-----|-----------|---------|--------|--------|
| 3 3 3 6 | 5 6 0 4 1 0 6 0 | 0 1 | C L 0 2 4 | D F L | Y | K |

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>