

TECHNICAL INFORMATION N°2003 - 54

Chassis : ITC008

Symptom / Problem observed :


A vertical jitter appears after a certain time or immediately after the switch on.

Cause :

The capacitor CF004 is defective.

Solution :

- Replace CF004 capacitor by another of the same value (1nF 50V) **PART No 10138550**.



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 3 5 3	1 0 1 3 8 5 5 0	0 1	C F 0 0 4	D F L	Y	A

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>