


TECHNICAL INFORMATION N°2006 - 39

Chassis : F21182 (ITC008)

Symptom / Problem Observed :
Horizontal over scanning.

Solution :

- Change CL024 capacitor from 330nF to 360nF 5% 250V (**PART No 36161080**).
- Change the resistor in position RL002 from 75K Ω to 91K Ω 5% 0.250W (**PART No 13080620**)



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	3 6 1 6 1 0 8 0	0 1	C L 0 2 4	D F L	Y	K
	1 3 0 8 0 6 2 0	0 1	R L 0 0 2	D F L	Y	K

You do not need to write anything in the white boxes.



THOMSON Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>