

TECHNICAL INFORMATION N°2005 - 23

Chassis : 29DM182 (ITC008 - With Panasonic tube)


Symptom / Problem Observed :

Adjustment range improvement of horizontal amplitude.

Solution :

On East-West module :

- Change CL145 capacitor from 22 μ F to 47 μ F 50V (**PART No 80429460**).
- Change DL142 diode 1N4148 by the new model BAT85 (**PART No 16008140**).
- Change DL143 zener diode from 7.5V to 8.2V type BZX55C8V2 (**PART No 11073660**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 3 2 X	8 0 4 2 9 4 6 0	0 1	C L 1 4 5	D F L	Y	A
	1 6 0 0 8 1 4 0	0 1	D L 1 4 2	D F L	Y	A
	1 1 0 7 3 6 6 0	0 1	D L 1 4 3	D F L	Y	A

You do not need to write anything in the white boxes. ☐



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>