

TECHNICAL INFORMATION N°2006 - 19

Chassis : ITC008

28" 16/9 with Samsung or vidéocolor tube and DST Shekou


29" 4/3 with Samsung tube and DST Shekou

Symptom / Problem Observed :

Vertical red strips on screen and menu deformation.

Solution :

Change CL006 capacitor from 120pF to 56pF 50V **PART No 10137330**.



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 3 4 X	1 0 1 3 7 3 3 0	0 1	C L 0 0 6	D F L	Y	A

You do not need to write anything in the white boxes.



THOMSON Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>