

## TECHNICAL INFORMATION N°2006 - 21

### Chassis : ITC008 (29" set)

#### Symptom / Problem Observed :

Incorrect picture geometry in 16/9 mode.  
(Horizontal over scanning, Horizontal Pincushion).

#### Solution :

##### On EWM board :

- Change RL156 resistor from 470Ω to 270Ω 5% 0.250W (**PART No 15007430**).
- Change RL157 resistor from 1KΩ to 270Ω 5% 0.250W (**PART No 15007430**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;  
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 3 3 X	1 5 0 0 7 4 3 0	0 1	R L 1 5 6	D F L	Y	A
	1 5 0 0 7 4 3 0	0 1	R L 1 5 7	D F L	Y	A

You do not need to write anything in the white boxes.



**THOMSON Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>