

## TECHNICAL INFORMATION N°2004 - 11

### Chassis : 33MF220G (ITC008)

#### Symptom / Problem observed :

Horizontal over scanning in 16/9 mode.

#### Solution :

##### On East-West Board :

- Change RL156 from 240Ω to 470Ω 5% 0.300W (**PART N°10262390**).
- Change RL157 from 240Ω to 820Ω 5% 0.250W (**PART N°80439900**).

**IRIS Code :** The code mentioned below must be used to report the failure on the warrantee claims form;  
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	1 0 2 6 2 3 9 0	0 1	R L 1 5 6	D F L	Y	A
	8 0 4 3 9 9 0 0	0 1	R L 1 5 7	D F L	Y	A

You do not need to write anything in the white boxes.



**THOMSON multimedia Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>