

TECHNICAL INFORMATION N°2004 - 29


Chassis : ITC008

Symptom / Problem Observed :

In standby mode, the set doesn't start when a device (e-i VCR), connected to the scart socket, is turned on.

Solution :

Change DP057 zener diode from 5V to 9V1 type BZX55C9V1 (**PART No 90578100**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 1 1 G	9 0 5 7 8 1 0 0	0 1	D P 0 5 7	P S	Y	A

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>