


TECHNICAL INFORMATION N°2005 - 46

Chassis ITC008 - 21" XF model (With LG Tube A51ERF135X80 and DST Orega)

Symptom / Problem Observed :
Horizontal over scanning.

Solution :
- Change CL024 capacitor from 360nF to 390nF 5% 250V (**PART No 20053100**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;

we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	2 0 0 5 3 1 0 0	0 1	C L 0 2 4	D F L	Y	K

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>