

## TECHNICAL INFORMATION N°2004 - 12

### Chassis : 21DC150S (ITC008)

#### Symptom / Problem Observed :

Difference of sound level in the speakers between the sound coming from AV source (i.e. VCR) and that from a RF Channel.

#### Solution :

- Add resistor 12K $\Omega$  5% 0.100W at position CS118 (**PART N°10135030**).
- Change RS 104 and RS106 from 1K $\Omega$  to 8.2K $\Omega$  5% 0.100W (**PART N°10136000**).
- Change RJ101 from 100 $\Omega$  to 4.7K $\Omega$  5% 0.100W (**PART N°10135940**).

**IRIS Code :** The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

| Symptom | Part code number | Qty | Position  | Section | D.Code | R.Code |
|---------|------------------|-----|-----------|---------|--------|--------|
| 1 5 2 X | 1 0 1 3 5 0 3 0  | 0 1 | C S 1 1 8 | A P A   | Z      | K      |
|         | 1 0 1 3 6 0 0 0  | 0 1 | R S 1 0 4 | A P A   | Y      | A      |
|         | 1 0 1 3 6 0 0 0  | 0 1 | R S 1 0 6 | A P A   | Y      | A      |
|         | 1 0 1 3 5 9 4 0  | 0 1 | R J 1 0 1 | A P A   | Y      | A      |

You do not need to write anything in the white boxes. ☐



**THOMSON multimedia Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>