

TECHNICAL INFORMATION N°2004 - 21


Chassis : ITC008
14MG115 - 14MG135 - 14MK142
20DG132 - 20MG132 - 21MG132

Symptom / Problem Observed :

Difference of sound level in the speakers between the sound coming from AV source (i.e. VCR) and that from a RF Channel.

Solution :

- Delete the resistor in position CS116.
- Change CS118 from 15K Ω to 12K Ω 5% 0.100W (**PART N° 10135030**).
- Change RS104 and RS106 from 1K Ω to 8.2K Ω 5% 0.100W (**PART N°10136000**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 5 2 X	1 0 1 3 5 0 3 0	0 1	C S 1 1 8	A P A	Y	A
	1 0 1 3 6 0 0 0	0 1	R S 1 0 4	A P A	Y	A
	1 0 1 3 6 0 0 0	0 1	R S 1 0 6	A P A	Y	A

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
 30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>