

TECHNICAL INFORMATION N°2004 - 24

Chassis : 28DR222 (ITC008)

Symptom / Problem Observed :

Noise (PLOP) in loudspeakers after the mains supply is switch OF.

Solution :

- Replace the diode at location DP061 with a SB560 diode (**Part N° 20956430**).
- Replace the jumper link at location DS201 with a RGP15G diode (**Part N° 10272800**).
- Change resistor RS211 from 4.7KΩ to 47KΩ 5% 0.100W (**Part N° 10135220**).

IRIS Code: The code mentioned below must be used to report the failure on the warrantee claims form;
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
P 5 2 X	2 0 9 5 6 4 3 0	0 1	D P 0 6 1	P S U	Y	A
	1 0 2 7 2 8 0 0	0 1	D S 2 0 1	A P A	Y	A
	1 0 1 3 5 2 2 0	0 1	R S 2 1 1	A P A	Y	A

You do not need to write anything in the white boxes. ☐



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>