

TECHNICAL INFORMATION N°2004 - 53

Chassis : ITC008 (20" Chunghwa tube)


DF51135 - 20DG132 - 20MG100 - 20MG132 - 51135

Symptom / Problem Observed :

Horizontal over scanning.

Solution :

Change CL024 capacitor from 390nF to 440nF 5% 250V **PART No 43352100.**



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	4 3 3 5 2 1 0 0	0 1	C L 0 4 0	D F L	Y	A

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>