

## TECHNICAL INFORMATION N°2003 - 47


### Chassis : ITC008

#### Symptom / Problem observed :

After 2 or 3 working hours, the set switch OFF and switch ON again without apparent reason.  
(The symptom is repeated every 45 minutes)

#### Solution :

Remove the resistor in position RK006.



**IRIS Code :** The code mentioned below must be used to report the failure on the warrantee claims form;  
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 1 1 B				S F T	Y	J

You do not need to write anything in the white boxes.



**THOMSON multimedia Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>