

TECHNICAL INFORMATION N°2006 - 26

Chassis : ITC008

Note : The serial numbers concerned are from ZU2210370 to ZU2583634

Symptom / Problem Observed :

Risk of burnt fuse during the wake up of the set.

Solution :

Replace the fuse in position FP001 by a new one **PART No 48064700**.

IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 1 1 0	4 8 0 6 4 7 0 0	0 1	F P 0 0 1	P S U	Y	A

You do not need to write anything in the white boxes.



THOMSON Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>

2006/06