

## TECHNICAL INFORMATION N°2004 - 27

### Chassis : ITC008

- 14MG135
- 21DM182
- 21DR182
- 28DR222
- 28EX280T

### Symptom / Problem Observed :

Colour flashing on the screen.

### Solution :

Replace the software (IV001) with a new version S1.07, **Part N°35800380**.

**IRIS Code :** The code mentioned below must be used to report the failure on the warrantee claims form; we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 4 5 1	3 5 8 0 0 3 8 0	0 1	I V 0 0 1	S F T	1	2

You do not need to write anything in the white boxes.



**THOMSON multimedia Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>