


TECHNICAL INFORMATION N°2005 - 45

Chassis : 21MH182 - ITC008
(With Samsung tube A51QDX993X234 and DST Orega)

Symptom / Problem Observed :
Horizontal over scanning.

Solution :
- Change CL024 capacitor from 330nF to 290nF 5% 250V (**PART No 10777420**).



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;

we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
3 3 3 6	1 0 7 7 7 4 2 0	0 1	C L 0 2 4	D F L	Y	K

You do not need to write anything in the white boxes.



THOMSON multimedia Sales UK Limited
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>