


## TECHNICAL INFORMATION N°2006 - 14

Chassis : **21MX172 (ITC008)**  
(with Samsung tube and DST Shekou)

**Symptom / Problem observed :**  
Vertical red strips on screen and menu deformation.

**Solution :**  
Add a capacitor of 56pF 50V, in position CL006, **PART No 10137330**.



IRIS Code : The code mentioned below must be used to report the failure on the warrantee claims form;  
we have included it to make fault report easier and the data more reliable.

Symptom	Part code number	Qty	Position	Section	D.Code	R.Code
1 3 4 X	1 0 1 3 7 3 3 0	0 1	C L 0 0 6	D F L	Z	K

You do not need to write anything in the white boxes.



**THOMSON Sales UK Limited**  
30 Tower View, Kings Hill, West Malling, Kent. ME19 4NQ

44(0) 1732 520 920 - <http://www.thomson-network.com>