



30. 6. 2021 11:07




30. 6. 2021 11:07



30. 6. 2021 11:07



30. 6. 2021 11:08




30. 6. 2021 11:13

Pas de référence sur le gicleur,...!




30. 6. 2021 11:16



125/100 1,25 mm

30. 6. 2021 11:29



35/100

30. 6. 2021 12:00



30. 6. 2021 12:08

Remontage avec 4 vis BTR